
WIRING INSTRUCTIONS




WIRING SPECIFICATIONS						
Wire No.	Wire Color	Origin or Gauge	Length	Terminals, Connectors and 1 or 2 End Wire Preparation		
1	BLUE	CORD	70mm	STRIP 6mm		
2	BROWN	CORD	70mm	STRIP 6mm		
3	WHITE	FIELD		STRIP 6mm		
4	BLACK	FIELD		STRIP 6mm		
5	WHITE	FIELD		STRIP 5mm FOR T1		
6	WHITE	FIELD		STRIP 5mm FOR T1		
7	GREENYELLOW	CORD	117mm	STRIP 5mm FOR T1		

NOTE:

All leads must be held to \pm 3 mm. All field leads to be measured from and perpendicular to laminations. All lead lengths are before stripping.

TERMINAL DESCRIPTION						
Code	de Part No.					
T1	23-74-0841	3				
CONNECTOR DESCRIPTION						



(14)

(16)

(13)

9

Description No. Req. Fig. **Part Number** 22-68-0200 Switch Boot 2 23-66-1430 Switch 1 23-94-9915 3 Connector Lead 1 4 22-36-0150 Breaker 1 5 22-68-0210 **Breaker Boot** 1 6 22-33-0305 Suppressor 1 22-74-0050 7 Delay Circuit (CLD) 1 8 22-12-0200 1 **Enclosure** 9 06-82-7299 Screw 4 31-17-0155 10 Clamp 2 11 44-76-0140 Strain Relief 1 12 22-64-4075 Cord Set (220 V) 1 13 22-68-0190 Cover 1 14 12-98-3070 Instruction Plate 1 22-64-4085 15 Cord Set (Tool) 1 16 06-82-7326 4 Screw

Terminal Block

17

22-56-0480

NOTE:

3

5

(8)

Cover should mate flush with enclosure before driving the 4 cover screws. A gap indicates a misplaced wire or component.

Tighten breaker boot after installing cover.

> Extend cord jacket 9mm past clamp. (2 places)