

Version Explanation for 100443/CON-7013 BMSC

100443 – Obsolete


- First generation motor controller
- Known Issues: None
- If BMSC Fails:
 1. Replace with CON-7013.C
 2. Upgrade Software:
 - HhB - HHB-8144-X Rev. E or greater
 - HhB2 - HHB-8243-X Rev. C or greater
 - All other ovens: no software upgrade required



How to Identify
Transformer: Type A

CON-7013 Rev. B v2 – Obsolete


- Second generation motor controller
- Known Issues:
 - Good performance, but nuisance “F1” faults still occur
- If BMSC Fails (HhB or HhB2):
 - Upgrade Software:
 - HhB - HHB-8144-X Rev. E or greater
 - HhB2 - HHB-8243-X Rev. C or greater
- If BMSC Fails (all other ovens):
 - Replace with CON-7013.C



How to Identify
Supplier Revision: B
Software Version: Marked Out
PCB Revision: E
Transformer: Type B

CON-7013 Rev. A – Obsolete


- Second generation motor controller
- Known Issues:
 - “F1” faults occur at startup and while cooking at 100%
- If BMSC Fails:
 1. Replace with CON-7013.C
 2. Upgrade Software:
 - HhB - HHB-8144-X Rev. E or greater
 - HhB2 - HHB-8243-X Rev. C or greater
 - All other ovens: no software upgrade required



How to Identify
Supplier Revision: A
Software Version: 01.01
PCB Revision: D or E
Transformer: Type B

CON-7013 Rev. C – Active


- Second generation motor controller
- Known Issues: None




How to Identify
Supplier Revision: C
Software Version: 1.50
PCB Revision: J
Transformer: Type B (vendor 1: “XFMR5”) (vendor 2: “OBP/SMC”)

CON-7013 Rev. B v1– Obsolete

- Second generation motor controller
- Known Issues:
 - Better performance, but same issues as CON-7013 Rev. A
- If BMSC Fails:
 1. Replace with CON-7013.C
 2. Upgrade Software:
 - HhB - HHB-8144-X Rev. E or greater
 - HhB2 - HHB-8243-X Rev. C or greater
 - All other ovens: no software upgrade required



How to Identify
Supplier Revision: B
Software Version: 01.01
PCB Revision: F (Handwritten)
Transformer: Type B



Supplier Revision Detail