

Patch Release Note

Patch 86222-06 For Rapier Switches and AR800 Series Modular Switching Routers

Introduction

This patch release note lists the issues addressed and enhancements made in patch 86222-06 for Software Release 2.2.2 on existing models of Rapier L3 managed switches and AR800 Series L3 modular switching routers. Patch file details are listed in Table 1.

Table 1: Patch file details for Patch 86222-06.

Base Software Release File	86s-222.rez
Patch Release Date	30-Aug-2001
Compressed Patch File Name	86222-06.paz
Compressed Patch File Size	226776 bytes

This release note should be read in conjunction with the following documents:

- Release Note: Software Release 2.2.2 for Rapier Switches, AR300 and AR700 Series Routers, and AR800 Series Modular Switching Routers (Document Number C613-10313-00 Rev A) available from www.alliedtelesyn.co.nz/documentation/documentation.html.
- Rapier Switch Documentation Set for Software Release 2.2.1 available on the Documentation and Tools CD-ROM packaged with your switch, or from www.alliedtelesyn.co.nz/documentation/documentation.html.
- AR800 Series Modular Switching Router Documentation Set for Software Release 2.2.1 available on the Documentation and Tools CD-ROM packaged with your switching router, or from www.alliedtelesyn.co.nz/documentation/documentation.html.



WARNING: Using a patch for a different model or software release may cause unpredictable results, including disruption to the network. Information in this release note is subject to change without notice and does not represent a commitment on the part of Allied Telesyn International. While every effort has been made to ensure that the information contained within this document and the features and changes described are accurate, Allied Telesyn International can not accept any type of liability for errors in, or omissions arising from the use of this information.

Features in 86222-06

Patch 86222-06 includes all issues resolved and enhancements released in previous patches for Software Release 2.2.2, and the following enhancements:

PCR: 01188 **Module: SWI** **Network affecting: No**

The power supply voltages of the base board PHYs on a Rapier G6 are controlled by a PHY register value, which was incorrectly set. This issue has been resolved.

PCR: 01190 **Module: PIM** **Network affecting: No**

In PIM Dense Mode, if a data stream started before PIM hello messages were exchanged, the receiver did not get the data stream. This issue has been resolved.

PCR: 01192 **Module: SWI** **Network affecting: No**

The Rapier G6 base ports sometimes experienced spurious link up or link down events. This issue has been resolved.

Features in 86222-05

Patch file details for Patch 86222-05 are listed in Table 2.

Table 2: Patch file details for Patch 86222-05.

Base Software Release File	86s-222.rez
Patch Release Date	24-Aug-2001
Compressed Patch File Name	86222-05.paz
Compressed Patch File Size	223728 bytes

Patch 86222-05 includes all issues resolved and enhancements released in previous patches for Software Release 2.2.2, and the following enhancements:

PCR: 01148 **Module: SWI** **Network affecting: No**

A39 copper uplink modules in the Rapier G6 sometimes experienced spurious link up or link down events. This issue has been resolved.

PCR: 01157 **Module: CORE** **Network affecting: No**

The enterprise MIB now supports objects for power supply monitoring.

PCR: 01162 **Module: PKI** **Network affecting: No**

Certificates containing *GeneralisedTime* with the year in YYYY format are now parsed correctly. The *keyUsage* field of certificates is now parsed correctly when only one byte has been specified. The *CRL update time* is now displayed correctly in hours. If the *username* and *password* parameters are present the *location* parameter must be present and appear before the *username* and *password* parameters. Certificates with signatures of 257 bytes are now correctly parsed. Certificates added from a configuration script are now processed correctly.

PCR: 01170 Module: IPv6 Network affecting: No

A fatal error occurred if an IPv6 interface was deleted while packets were being transmitted. The number of current interfaces was not being updated correctly when a new IPv6 interface was added. As a result, after multiple additions and deletions, no more IPv6 interfaces could be added. These issues have been resolved.

PCR: 01176 Module: PKI Network affecting: No

The CREATE CONFIG command now adds PKI certificates to the script in the same order that they were originally added to the certificate database.

PCR: 01177 Module: PKI Network affecting: No

PKI certificates are now periodically checked (once per hour) to verify that they are still valid.

PCR: 01178 Module: IPSEC Network affecting: No

IPCOMP SA's which have the reserved CPI "3" are no longer deleted by ISAKMP delete messages.

PCR: 01179 Module: SWI Network affecting: No

When a VLAN was created and then destroyed on the G6 or G6F, the VTABLE was corrupted. This has been fixed.

PCR: 01181 Module: DHCP Network affecting: No

DHCP failed to send request messages when it was in a rebinding or renewing state. This issue has been resolved.

PCR: 01185 Module: SWI Network affecting: No

In some extreme traffic conditions the switch could lock up, preventing switching of any traffic. This issue has been resolved.

PCR: 01186 Module: FIREWALL Network affecting: No

When large numbers of sessions were being handled the firewall would become overly aggressive in restricting new sessions. The *Active TCP Opens* field in the output of the SHOW FIREWALL POLICY would show a very high number (42×10^8). This issue has been resolved.

PCR: 01187 Module: IPG Network affecting: No

If the IGMP table was empty and a timeout was set, a fatal error occurred. This issue has been resolved.

Features in 86222-04

Patch file details for Patch 86222-04 are listed in Table 3.

Table 3: Patch file details for Patch 86222-04.

Base Software Release File	86s-222.rez
Patch Release Date	24-Aug-2001
Compressed Patch File Name	86222-04.paz
Compressed Patch File Size	220220 bytes

Patch 86222-04 includes all issues resolved and enhancements released in previous patches for Software Release 2.2.2, and the following enhancements:

PCR: 01124 Module: PKI Network affecting: No

Message protection validation failures would occur intermittently. This issue has been resolved.

PCR: 01136 Module: ISAKMP Network affecting: No

ISAKMP now interoperates with other vendor's products in aggressive mode exchanges.

PCR 01138 Module: CORE, SWI Network affecting: No

Support has been added for the 8624XL-80 switch with -48VDC power supply.

PCR: 01152 Module: FIREWALL Network affecting: No

In a dual policy configuration, the firewall would lock up under load. The firewall would also mistakenly report SYN attacks. These issues have been resolved.

PCR: 01159 Module: PIM Network affecting: No

The CREATE CONFIG command generated duplicate PIM interface configuration command lines. This issue has been resolved.

PCR: 01162 Module: PKI Network affecting: No

Certificates containing *GeneralisedTime* with the year in YYYY format are now parsed correctly. The *keyUsage* field of certificates is now parsed correctly when only one byte has been specified. The *CRL update time* is now displayed correctly in hours. If the *username* and *password* parameters are present the *location* parameter must be present and appear before the *username* and *password* parameters.

PCR: 01165 Module: DHCP Network affecting: No

The DHCP server now correctly allocates addresses to clients running Apple Open Transport 2.5.1 or 2.5.2.

PCR: 01166 Module: FIREWALL Network affecting: No

Both public and private access could be configured on the same interface on a policy. This issue has been resolved.

PCR: 01167 **Module: ENCO** **Network affecting: No**

RSA encryption is now periodically suspended to ensure other processes get some CPU time during large RSA calculations.

PCR: 01169 **Module: ISAKMP** **Network affecting: No**

The CREATE ISAKMP command now checks that the key specified by the LOCALRSAKEY parameter actually exists in the ENCO module.

PCR: 01171 **Module: ETH, TRIGGER** **Network affecting: No**

The INTERFACE parameter of the CREATE TRIGGER and SET TRIGGER commands now supports Ethernet interfaces. Ethernet interface events can now generate triggers.

PCR: 01173 **Module: Telnet** **Network affecting: No**

The Telnet server's listen port can now be configured to a number in the range 1 to 65535, excluding any ports already assigned as listen ports.

PCR: 01174 **Module: Firewall** **Network affecting: No**

The CREATE CONFIG command sometimes generated scripts for rule commands with GBLIP=0.0.0.0 when this was not necessary. This issue has been resolved.

Features in 86222-03

Patch file details for Patch 86222-03 are listed in Table 4.

Table 4: Patch file details for Patch 86222-03.

Base Software Release File	86s-222.rez
Patch Release Date	8-Aug-2001
Compressed Patch File Name	86222-03.paz
Compressed Patch File Size	205828 bytes

Patch 86222-03 includes all issues resolved and enhancements released in previous patches for Software Release 2.2.2, and the following enhancements:

PCR: 01112 **Module: IPG** **Network affecting: No**

DNS response packets with corrupt length fields were causing a fatal error. This issue has been resolved.

PCR: 01139 **Module: IPG** **Network Affecting: No**

IP NAT caused a fatal error when an ARP wait timer timed out and tried to send a host unreachable message. This issue has been resolved.

PCR: 01147 **Module: STT** **Network affecting: No**

The router was restarting after a "teardrop" attack on the STT listen port. This issue has been resolved.

PCR: 01150 **Module: FIREWALL** **Network affecting: No**

The entry aging process now works correctly even when there are large numbers of firewall entries to be aged.

PCR: 01153 **Module: IPG** **Network affecting: No**

The command `SHOW IP DEBUG=n` was entered, where n was one greater than the number of items in the IP debug queue resulted in a fatal error. This issue has been resolved.

Features in 86222-02

Patch file details for Patch 86222-02 are listed in Table 5.

Table 5: Patch file details for Patch 86222-06.

Base Software Release File	86s-222.rez
Patch Release Date	26-Jul-2001
Compressed Patch File Name	86222-02.paz
Compressed Patch File Size	202564 bytes

Patch 86222-02 includes all issues resolved and enhancements released in previous patches for Software Release 2.2.2, and the following enhancements:

PCR: 01081 **Module: FIREWALL** **Network affecting: No**

When an interface on the firewall was configured with a global IP address of 0.0.0.0, outgoing packets from the private interface to the public interface sometimes caused a fatal error. This issue has been resolved.

PCR: 01126 **Module: PKI** **Network affecting: No**

Re-validation of temporary CA certificates now works correctly.

PCR: 01128 **Module: IPG** **Network affecting: No**

A fatal error occurred when IGMP received a *Join* message and attempted to forward the *Join* message to other switch ports. This issue has been resolved.

PCR: 01131 **Module: CORE** **Network affecting: No**

The `SHOW CPU` command sometimes displayed incorrect CPU utilisation figures. Typically a value of about 74% was reported when in fact the CPU was almost idle. This issue has been resolved.

PCR: 01134 **Module: GUI** **Network affecting: No**

Port parameters can now be set correctly using the Layer 3 Switch GUI.

PCR: 01135 **Module: GUI,INST** **Network affecting: No**

Clicking the *Apply* button on a Layer 3 Switch GUI page caused the switch to lock up if no configuration file was set, but `boot.cfg` was present. This issue has been resolved.

Availability

Patches can be downloaded from the Software Updates area of the Allied Telesyn web site at www.alliedtelesyn.co.nz/support/updates/patches.html. A licence or password is not required to use a patch.