




# Wall-Mounted Dewpoint Sensor

## Product Information Sheet


210-2002

- Highlight the input-point the sensor is attached to and press **F1** (SETUP) to set up the input, or press **Enter** to open the Actions Menu and select **5** (Setup). (If using an Einstein, select an input point and press **F7** (SETUP IN) to open the Analog Input screen.)



*E2 Actions Menu for Selected Input*


- Select Analog to set up the input as analog. The Analog Input screen will display:



*Set Sensor Type to Linear*


- Once on the Analog Input screen, move the cursor to the **Sensor Type** field, press **F4** (LOOK UP), and set to **Linear**. (If using

an Einstein, press **F7** (LOOK UP) and set to **Linear**.)



*Option List Selection Menu For Sensor Type*

- Move cursor to **Select Eng. Units** and press **F4** (LOOK UP). Set this field to **DF** (for Degrees Fahrenheit). (If using an Einstein, press **F7** (LOOK UP) and set to **DF**.)



*Set Sensor Type to Linear*

- Then set the following sensor properties:
  - Set the **Modify** field to: **EndPoint**. (If using an Einstein, press **F7** (LOOK UP) and set to **EndPoint**.)

# Wall-Mounted Dewpoint Sensor

## Product Information Sheet

210-2002

- Set the **Low End Point** field to **0**.
- Set the **High End Point** field to **5.0**.
- Set the **Low Eng. Units** field to **0**.
- Set the **High Eng. Units** field to **80**.
- Set the **Low End Limit** field to **-0.5**.
- Set the **High End Limit** field to **6.5**.

10-16-03 RM-300 Unit 1 CATS 9AT: 7 0H: 94 10:35:16  
ANALOG INPUT FULL ALARM

Board/Point # : 2.1  
Point Name : .AT.01.02.01  
Sensor Type : Linear  
Select Eng. Units: DF  
Default on Open : NONE  
Default on Short : NONE  
Default Other : NONE  
Change Delta : 0.0100  
0  
Mult. Factor : 1.0  
Sensor Offset : 0

Modify Sensor Properties  
Modify EndPoint  
Low End Point: 0.00000 V Low Eng. Units : 0.000000  
High End Point: 5.00000 V High Eng. Units: 80.000000  
Low End Limit: -0.500000  
High End Limit: 6.500000

Controller Application Input  
OCCURANCY : : : L  
OUTPUT : : : L

Enter Board/Controller | Analog Input Output

Analog Input Screen - Set Sensor Properties

### REFLECS

1. Log in to the controller.

RMCC 12:00  
10/02/03  
Password:   
Password required to change setpoints.  
Press ENT for viewing only...  
Enter Your Password (up to 6 digits)

REFLECS Login Screen

2. From the Main Menu, select **4 -Sensor Control**.

MAIN MENU 12:00

1-Pressure Control	5-Status
2-Condenser Control	6-Power Monitor
3-Circ/Defr Control	7-Configuration
4-Sensor Control	8-Graphs
	9-Alarms

SELECT NUMBER ENT=LOGOFF

### REFLECS Main Menu Screen

3. From the Sensor Control screen, select **2 - Setup**.

SENSOR CONTROL 12:00

1-Status	5-Logs
2-Setup	6-Alarm Overrides
3-Setpoints	7-Override Status
4-Alarms	8-Shut off Sched.
	9-I/O Control Modules

SELECT NUMBER 0=MENU

Sensor Control Screen

4. From the Select Sensor screen, choose the sensor you wish to set up:

--SELECT ITEM-- 12:00

01 SENS01	06 SENS06
02 SENS02	07 SENS07
03 SENS03	08 SENS08
04 SENS04	09 SENS09
05 SENS05	10 SENS10

Enter Item:  
Arrows to Move (ENT)accept (CLR)Escape


Select Item Screen

5. Once you select a sensor, the Sensor Setup screen opens. Enter a name for the sensor in the **Name** field (for example, DEWPOINT) and set the **Type** field to **Linear** by using the scroll keys or pressing the red button + the **8** (L) button.

SENSOR SETUP 12:00  
#:01 Status:OFF Name:DEWPOINT  
Type: Linear  
Logging Interval (HH:MM:SS): 00:03:00  
↑=PREV ↓=NEXT →=SET-DATA 0=MENU


Sensor Control Screen

6. Press **0** to go back to the Sensor Control screen. Select **3 -Setpoints** and then choose the sensor to set Gain and Offset.




*Sensor Control Screen*

7. Set **Gain** to **16**, **Offset** to **0** (the default) and enter degrees fahrenheit units into the **Eng. Unit** field (for example, type DEGF).




*Sensor Setpoints for Linear Input*

8. To check the sensor input value, press **0** to go back to the Sensor Control screen and select **1 -Status**.



*Sensor Setpoints for Linear Input*



*Sensor Status Screen – Sensor Value*

## Set Up Zero Calibration

The Zero Calibration mode allows the user to calibrate the sensor to a verified zero concentration of water vapor. For best results, allow the sensor to warm up for at least 10 minutes.

For zero calibration, all tubing should be connected between the gas bottle and the sensor inlet flow port. Before initiating calibration using the sensor keypad, the gas should be flowed to the sensor at a rate of 80-100 cc/minute for a period of five minutes.

Observe the following steps to set up Zero Calibration mode.

1. Attach the short hose to the bottom port on the flowmeter.
2. Attach the long hose to the top port on the flowmeter.
3. To ensure the meter is kept in the vertical position, secure the flowmeter to the side of the gas bottle using the supplied tie wrap.
4. Remove the protective cap from the nitrogen bottle and attach the gas regulator.
5. Attach the open end of the bottom hose (located on the flowmeter) to the gas regulator. Slide the hose far enough on the gas port to ensure a secure, airtight connection.
6. Insert the male luer fitting (located on the longer hose) into the calibration port, located on the bottom of the dewpoint sensor.
7. Verify that all components are installed correctly and initiate the calibration process by turning the knob on the regulator. Turn the knob until the indicator reaches 7 psi.
8. Turn the flowmeter knob until the floater reaches 80-100 cc/minute.
9. Allow the gas to flow for at least 5 minutes before proceeding.

# Wall-Mounted Dewpoint Sensor

## Product Information Sheet

210-2002


10. Press the **Clear** and **Enter** buttons together and hold for five seconds. The word CAL will appear in the topline of the LCD display:



11. Use the arrow buttons to toggle to the Zero Calibration mode.

**NOTE:** Prior to pressing the **Enter** button, the zero gas should be flowing to the dewpoint sensor for at least five minutes.

12. When **ZERO** is displayed, press the **Enter** button to initiate the calibration process.



13. Once the **Enter** button is pressed, the calibration process will take five to seven minutes during which time the green LED below the display will flash. Once calibration is completed, the sensor will revert to its normal display mode.

## Calibration Layout

Refer to the calibration topic of the manufacturer's manual for the sensor's zero calibration layout. Contact your CPC sales representative for calibration kit (P/N 210-2005) purchasing information.

Emerson™, Emerson. Consider It Solved™ and Emerson Climate Technologies™ logos are trademarks and service marks of Emerson Electric Co. Intelligent Store™ is a trademark of Emerson Climate Technologies. All other trademarks are the property of their respective owners.  
© 2011 Emerson Climate Technologies, Inc. All rights reserved.

Vaporstat™ is a registered trademark of Telaire company.



[www.emersonretailsolutions.com](http://www.emersonretailsolutions.com)

