


# How to develop the ARM 64bit board, Samsung TM2 with Exynos5433

---

Chanwoo Choi [cw00.choi@samsung.com](mailto:cw00.choi@samsung.com)

Seung-Woo Kim [sw0312.kim@samsung.com](mailto:sw0312.kim@samsung.com)

SW Center,  
Samsung Electronics



# Who are we?

## Chanwoo Choi

Kernel Maintainer of EXTCON and Exynos Clock.  
Maintainer of Tizen Kernel.

<cw00.choi@samsung.com>

## Seung-Woo Kim

Kernel Maintainer of Exynos DRM.  
Maintainer of Tizen Kernel.

<sw0312.kim@samsung.com>

- What is Samsung TM2?
- What we do for ARM 64bit?
- What are difficult issues on TM2?

# What is Samsung TM2?

---



## Samsung TM2 (Tizen Mobile)

- TM2 is the mobile reference board for Tizen.
- Uses the Samsung Exynos5433 SoC.
- ARMv8 architecture and supporting 64bit.

## Development history of TM2

- Tizen starts supporting 64bit on ARM Juno board.
- TM2 board development started on Oct. 2014, based on Exynos5433 announced on Sep. 2014.
- Now, Tizen supports almost all functionalities except for modem.
- First patch posted on mainline on Nov. 2014.

# Samsung TM2 Kernel information

- Tizen git repository with v4.1 kernel
  - More than 1,300 patches for Samsung TM2 based on Exynos5433.
  - <https://review.tizen.org/git/?p=platform/kernel/linux-exynos.git;a=shortlog;h=refs/heads/tizen>

projects / platform / kernel / linux-exynos.git / shortlog					
<a href="#">summary</a>   <a href="#">shortlog</a>   <a href="#">log</a>   <a href="#">commit</a>   <a href="#">commitdiff</a>   <a href="#">tree</a>					
first · prev · next					
platform/kernel/linux-exynos.git					
12 hours ago	Andrzej Hajda	drm/panel/s6e3ha2: remove redundant definition of VINT_...	56/87156/4	tizen	
12 hours ago	Andrzej Hajda	drm/panel/s6e3ha2: fix includes	55/87155/4		
12 hours ago	h.sandeep	Bluetooth: Add MGMT tizen_handlers and TIZEN_OP_BASE_CODE.	23/86423/4		
13 hours ago	Sudha Bheemanna	Bluetooth: Add "TIZEN_BT" flag	72/85072/8		
11 days ago	Seung-Woo Kim	drm/exynos/hdmi: workaround to check invalid modes...	87/87187/3	accepted/tizen_common	accepted/tizen_iwi
11 days ago	Sylwester Nawrocki	Merge "Enable dummy_hcd and FunctionFS in tm2 config...			
12 days ago	Hoegeun Kwon	arm64: dts: exynos5433: add sleep state for BCM4773...	15/87015/4		

# Patches on Linux Kernel mailing list

- More than 250 patches for TM2 and Exynos5433 including old versions.

- [https://patchwork.kernel.org/project/linux-samsung-soc/list/?q=exynos5433&state=\\*%26archive=both](https://patchwork.kernel.org/project/linux-samsung-soc/list/?q=exynos5433&state=*%26archive=both)

Filters: Search = exynos5433			
Patch	A/R/T	Date	Submitter
[v7,2/2] ASoC: samsung: Add machine driver for Exynos5433 based TM2 board	- 1 -	2016-09-02	<a href="#">Sylwester Nawrocki</a>
[v6,2/2] ASoC: samsung: Add machine driver for Exynos5433 TM2 board	- - -	2016-09-02	<a href="#">Sylwester Nawrocki</a>
[5/5] clocks: exynos5433: add runtime pm support	- - -	2016-09-01	<a href="#">Marek Szymowski</a>
[v2,7/7] arm64: dts: exynos: Add dts file for Exynos5433-based TM2E board	1 2 -	2016-08-24	<a href="#">Chanwoo Choi</a>
[v2,6/7] arm64: dts: exynos: Add dts file for Exynos5433-based TM2 board	- 2 -	2016-08-24	<a href="#">Chanwoo Choi</a>
[v2,5/7] arm64: dts: exynos: Add dts files for Samsung Exynos5433 64bit SoC	- 1 -	2016-08-24	<a href="#">Chanwoo Choi</a>
[v2,4/7] pinctrl: samsung: Add GPF support for Exynos5433	1 - -	2016-08-24	<a href="#">Chanwoo Choi</a>

- [https://patchwork.kernel.org/project/linux-samsung-soc/list/?q=TM2&state=\\*%26archive=both](https://patchwork.kernel.org/project/linux-samsung-soc/list/?q=TM2&state=*%26archive=both)

- More than 100 patches for TM2 and Exynos5433 have been merged.



# Samsung Exynos5433


- Exynos5433 appeared on Sep. 2014.

Module	Description
CPU	Octal Core CPU - Quad Cortex-A57 1.9GHz + Quad Cortex-A53 1.3GHz
Memomy	Memory bandwidth 1066MHz
Display	WQXGA (2560 x 1600) or WQHD (2560 x 1440)
Video	1080p 120-frame and UHD 30-frame
GPU	3D graphics hardware
High speed interface	PCIe (Peripheral Component Interconnect Express) LLI (Low Latency Interface) eMMC 5.1 USB 3.0



# What is Tizen ?



[www.tizen.org](http://www.tizen.org)



# Tizen on TM2



## CPU Benchmark result on TM2

- With Dhrystone, ARM 64bit shows better performance than ARM 32bit.
  - Dhrystone : 20% improvement on ARM 64bit

Benchmark Tools	Status	ARM 64bit	ARM 32bit
Dhrystone	DMIPS per second	12626582.4	10549179.0

# What we do for ARM 64bit?

---

for 64bit

for CPU cores



# ARMv8

- ARMv8 architecture support the 64bit.
- What are the difference between 32bit and 64bit?
  - Support the 64bit memory map
  - PSCI (Power State Coordinate Interface)

# What we do for ARM 64bit?

---

**for 64bit**

for CPU cores



# 64bit memory address mapping

- The bootloader should pass the physical memory address through ATAG\_MEM parameter with 64bit address.
  - 'mem=<size>[KM][,@<phys\_offset>]
- Memory node in TM2

```
/*  
 * start address      : 0x00000000_20000000  
 * memory bank size  : 0x00000000_c0000000  
 */  
memory@20000000 {  
    device_type = "memory";  
    reg = <0x0 0x20000000 0x0 0xc0000000>;  
};
```

The exynos5433-tm2.dtsi include the memory Device-Tree node.



## ARM drivers for 64bit : case of exynos-iommu

- SYSMMU v5 of exynos5433
  - Supporting 36bit physical address space
  - Shifting all page entry values by 4bits
  - iommu: exynos: add support for v5 SYSMMU (merged)

## ARM drivers for 64bit : case of s5p-mfc

- No 64bit considered address/offset size
  - media: s5p-mfc: fix mmap support for 64bit arch (merged)
    - Fix offset base depends on the systems architecture
  - media: s5p-mfc: fix broken pointer cast on 64bit arch (merged)
    - Remove pointer casting with fixed 32bit size

# ARM drivers for 64bit : case of dw\_mmc exynos

- AArch64 gcc bug in right-shift

```
s8 i;  
u8 c, __c;  
  
c = 0x7f;  
  
for (i = 0; i < 8; i++) {  
    __c = ror8(c, i);  
}
```

# expected

```
i == 0 → __c == 0x7f  
i == 1 → __c == 0xbf  
i == 2 → __c == 0xdf  
i == 3 → __c == 0xef  
i == 4 → __c == 0xf7  
i == 5 → __c == 0xfb  
i == 6 → __c == 0xfd  
i == 7 → __c == 0xfe
```

# result

```
i == 0 → __c == 0x7f 0111_1111  
i == 1 → __c == 0x3f 0011_1111  
i == 2 → __c == 0x1f 0001_1111  
i == 3 → __c == 0x0f 0000_1111  
i == 4 → __c == 0x07 0000_0111  
i == 5 → __c == 0x03 0000_0011  
i == 6 → __c == 0x01 0000_0001  
i == 7 → __c == 0x00 0000_0000
```

- Workaround from kernel in early stage
- Fixed with GCC patch

## Runtime checker: KASAN

- Kernel Address SANitizer
  - For ARM 64bit, since v4.3
  - CONFIG\_KASAN
- Can detect out-of-bounds accesses and use-after-free bugs.

# KASAN – case of extcon-max77843

- extcon: max77843: add guard element in array (fixed from tizen devel tree)
  - <https://review.tizen.org/git/?p=platform/kernel/linux-exynos.git;a=commitdiff;h=5ec7e9f3010a9254b89c3307385a8bda658d37cb>

BUG: KASan: out of bounds access in extcon\_dev\_register+0xc0/0x978 at addr fffffffc001bcc440

page dumped because: kasan: bad access detected

Address belongs to variable max77843\_extcon\_cable+0x60/0xf00

Call trace:

[...]

[<ffffffc00021e9ec>] kasan\_report+0x44/0x50

[<ffffffc00021d2dc>] \_\_asan\_load8+0x94/0xb0

[<ffffffc000a78904>] extcon\_dev\_register+0xbc/0x978

[<ffffffc000a791f8>] devm\_extcon\_dev\_register+0x38/0x90

[<ffffffc000a7cab8>] max77843\_muic\_probe+0x1e0/0x5f0

[...]

Memory state around the buggy address:

ffffffc001bcc300: 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00

ffffffc001bcc380: 00 00 00 00 00 00 00 00 fa fa fa fa 00 00 00 00

>ffffffc001bcc400: 00 00 00 00 00 00 00 00 fa fa fa fa 00 00 00 00

^

ffffffc001bcc480: 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00

ffffffc001bcc500: 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00

```
@@ -149,6 +149,7 @@ static const char *max77843_extcon_cable[] = {  
...  
+     NULL,  
};
```

# KASAN – case of fimc-is

- fimc-is: fix wrong index access for dt child nodes (fixed from tizen devel tree)
  - <https://review.tizen.org/git/?p=platform/kernel/linux-exynos.git;a=commit;h=f612545917b4b303d115655c7e4e5814b4969f15>

```
BUG: KASan: use after free in fimc_is_parse_children_dt+0x6c/0xe8 at
addr fffffffc08d27ffa8
page dumped because: kasan: bad access detected
Call trace:
[...]
```

[<ffffffc00021e9ec>] kasan\_report+0x44/0x50  
[<ffffffc00021d38c>] \_\_asan\_store8+0x94/0xb0  
[<ffffffc000991900>] fimc\_is\_parse\_children\_dt+0x68/0xe8  
[<ffffffc000959368>] fimc\_is\_probe+0xc0/0xed8  
[...]

Memory state around the buggy address:

```
ffffffc08d27fe80: ff ff ff ff ff ff ff ff ff ff ff ff ff ff ff
ffffffc08d27ff00: ff ff ff ff ff ff ff ff ff ff ff ff ff ff ff
>ffffffc08d27ff80: ff ff ff ff ff ff ff ff ff ff ff ff ff ff ff
                    ^
ffffffc08d280000: 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00
ffffffc08d280080: 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00 00
```

```
...
i = of_alias_get_id(child, "fimc-lite");
- if (i >= 0 || i < FIMC_IS_MAX_NODES)
+ if (i >= 0 && i < FIMC_IS_MAX_NODES)
    core->lite_np[i] = child;

i = of_alias_get_id(child, "csis");
- if (i >= 0 || i < FIMC_IS_MAX_NODES)
+ if (i >= 0 && i < FIMC_IS_MAX_NODES)
    core->csis_np[i] = child;
...
```

## Runtime checker: UBSAN

- Undefined Behavior SANitizer
  - For ARM 64bit, since v4.5
  - CONFIG\_UBSAN / CONFIG\_UBSAN\_SANITIZE\_ALL
  - Can detect overflows, shift out-of-bounds, array out-of-bounds and more undefined behaviors.

# UBSAN – case of dwmmc

- mmc: dw\_mmc: remove UBSAN warning in dw\_mci\_setup\_bus() (merged to mainline)

UBSAN: Undefined behaviour in drivers/mmc/host/dw\_mmc.c:1102:14  
shift exponent 250 is too large for 32-bit type 'unsigned int'

Call trace:

```
[<ffffff90080908a8>] dump_backtrace+0x0/0x380
[<ffffff9008090c3c>] show_stack+0x14/0x20
[<ffffff90087457b8>] dump_stack+0xe0/0x120
[<ffffff90087b1360>] ubsan_epilogue+0x18/0x68
[<ffffff90087b1a94>] __ubsan_handle_shift_out_of_bounds+0x18c/0x1bc
[<ffffff9008d89cb8>] dw_mci_setup_bus+0x3a0/0x438
[...]
```

UBSAN: Undefined behaviour in drivers/mmc/host/dw\_mmc.c:1132:27  
shift exponent 250 is too large for 32-bit type 'unsigned int'

Call trace:

```
[<ffffff90080908a8>] dump_backtrace+0x0/0x380
[<ffffff9008090c3c>] show_stack+0x14/0x20
[<ffffff90087457b8>] dump_stack+0xe0/0x120
[<ffffff90087b1360>] ubsan_epilogue+0x18/0x68
[<ffffff90087b1a94>] __ubsan_handle_shift_out_of_bounds+0x18c/0x1bc
[<ffffff9008d89c9c>] dw_mci_setup_bus+0x384/0x438
[...]
```

```
- if ((clock << div) != slot->__clk_old || force_clkinit)
-     dev_info(&slot->mmc->class_dev,
-             "Bus speed (slot %d) = %dHz (slot req %dHz, actual %dHz div = %d)\n",
-             slot->id, host->bus_hz, clock,
-             div ? ((host->bus_hz / div) >> 1) :
-             host->bus_hz, div);
- ...
- /* keep the clock with reflecting clock divisor */
- slot->__clk_old = clock << div; # div == 250
```



# UBSAN – case of pinctrl-exynos

- pinctrl: samsung: fix wakeup irq for extended eint (fixed from tizen devel tree)
  - <https://review.tizen.org/git/?p=platform/kernel/linux-exynos.git;a=commitdiff;h=367c75d2942b5fadf6faf92d06d096deb72de945;hp=ffeae979bfb99e666e7d9801a57eeac9b6962fad>

UBSAN: Undefined behaviour in drivers/pinctrl/samsung/pinctrl-exynos.c:376:26  
shift exponent 8217 is too large for 64-bit type 'long unsigned int'

Call trace:

```
[<fffffc00008f440>] dump_backtrace+0x0/0x218
[<fffffc00008f668>] show_stack+0x10/0x20
[<fffffc00159f3b8>] dump_stack+0x80/0xfc
[<fffffc00159f558>] ubsan_epilogue+0x10/0x6c
[<fffffc00159fe38>] __ubsan_handle_shift_out_of_bounds+0x188/0x1bc
[<fffffc000785514>] exynos_wkup_irq_set_wake+0x104/0x138
[<fffffc0001647b0>] set_irq_wake_real+0x70/0xc0
[<fffffc000164a70>] irq_set_irq_wake+0x158/0x1b0
[...]
```

```
- unsigned long bit = 1UL << (2 * bank->eint_offset + irqd->hwirq);    # 8217
...
- EXYNOS5433_PIN_BANK_EINTW_EXT(4, 0x060, "gpf3", 0x100c),
```

# What we do for ARM 64bit?

---

for 64bit

for **CPU cores**



# PSCI (Power State Coordinate Interface)


- Standard interface for power management by ARM.
- The aim of this standard is to ease the integration between supervisory software from different vendors working at different privilege levels.
- Generalization of the code for Power Management.

# Power management of PSCI

- Power management scenarios:
  - Core idle management (suspend, idle)
  - Core Hotplug
  - System Shutdown and reset.
  - big.LITTLE migration.
- PSCI does not cover DVFS (Dynamic Voltage Frequency Scaling) or device power management (such as GPUs).

# Exception Level of PSCI

- Version
  - major number : Define the different interface
  - minor number : Support the compatibility for low version
  - PSCI 0.1 (Samsung Exynos5433)
- ARM Exception Level



# Example for suspend with PSCI

- PSCI vs. Legacy method for suspend

```
static int psci_suspend_finisher(unsigned long index)
{
    struct psci_power_state *state = __this_cpu_read(psci_power_state);

    return psci_ops.cpu_suspend(state[index-1], virt_to_phys(cpu_resume));
}
```

in **arch/arm64/kernel/psci.c**

```
static int exynos_suspend(unsigned long resume_addr)
{
    writel(EXYNOS_SLEEP_MAGIC, S5P_VA_SYSRAM_NS + 0xC);
    writel(resume_addr, S5P_VA_SYSRAM_NS + 0x8);
    exynos_smc(SMC_CMD_SLEEP, 0, 0, 0);
    return 0;
}
```

in **arch/arm/mach-exynos/firmware.c**

# Example for CPU Hotplug with PSCI

- PSCI vs. Legacy method for CPU Hotplug

```
const struct cpu_operations cpu_psci_ops = {  
    .name      = "psci",  
    .cpu_init   = cpu_psci_cpu_init,  
    .cpu_prepare = cpu_psci_cpu_prepare,  
    .cpu_boot   = cpu_psci_cpu_boot,  
    .cpu_disable = cpu_psci_cpu_disable,  
    .cpu_die    = cpu_psci_cpu_die,  
    .cpu_kill   = cpu_psci_cpu_kill,  
};  
in arch/arm64/kernel/psci.c
```

```
struct smp_operation exynos_smp_ops __initdata = {  
    .smp_init_cpus      = exynos_smp_init_cpus,  
    .smp_prepare_cpus   = exynos_smp_prepare_cpus,  
    .smp_secondary_init = exynos_secondary_init,  
    .smp_boot_secondary = exynos_boot_secondary,  
    .cpu_idle           = exynos_cpu_idle,  
};  
in arch/arm/mach-exynos/platsmp.c
```

## How can I support the big.LITTLE core?

- Exynos5433 has the big.LITTLE core.
- Linux kernel includes the IKS (In-Kernel Switcher) from Linaro to support the scheduling for big.LITTLE cores.
- But, In-Kernel Switcher does not use the all cores at the same time.
  - To support the high-performance, need to use the all cores simultaneously.



# HMP (Heterogeneous Multi Processing)


- Linaro provides the HMP to support the big.LITTLE cores scheduling.
- All cores in the system can be used at the same time.
- HMP is supported only on Linux Kernel 3.10
  - Samsung TM2 support the HMP on Linux Kernel v4.1 (LTS version).

## HMP - sysbench test

- Take simple benchmark test to check the effect and performance improvement by HMP.
  - benchmark tool : sysbench with 6 threads
    - `sysbench64 --test=cpu --num-threads=6 --cpu-max-prime=300000 run`
  - profiling tool : ARM DS-5


# HMP - sysbench test without HMP

- Without HMP, the performance regression happens due to CPU contention.
  - CPU contention can happen if there are too many processes and not enough cores to handle them.
  - <http://infocenter.arm.com/help/index.jsp?topic=/com.arm.doc.dui0482h/BABFBJIC.html>



# HMP - sysbench test with HMP

- If CPU contention does not happen.
  - TM2 can use the whole resources to get high performance on specific scenario such as UHD video playback.



# What are the challenges on TM2?

---

**32bit process running on 64bit kernel**

Issues required to be discussed on mainline



## Personality 32bit setting on 64bit kernel (1/6)

- ARM 64bit kernel provides different information to userland according to the type of running user-process.
  - `uname -m`
  - `cat /proc/cpuinfo`
- The user process uses information provided by kernel such as thumb, fp and so on.

## Personality 32bit setting on 64bit kernel (2/6)

- Example,
  - The Unity engine on Tizen checks whether thumb mode is supported or not through `/proc/cpuinfo`.
  - ARM 64bit kernel doesn't include the 'thumb' on the feature `/proc/cpuinfo/`. But, ARM 64bit supports the 'thumb'.

```
root@localhost:~# cat /proc/cpuinfo
processor      : 0
BogoMIPS     : 48.00
Features      : fp asimd evtstrm aes pmull sha1 sha2 crc32
CPU implementer : 0x41
CPU architecture: 8
.....
```



## Personality 32bit setting on 64bit kernel (3/6)

- The 32bit user-process should set the PER\_LINUX32 personality type with 'personality()' function on runtime.
  - `personality(PER_LINUX32);`

```
#include <stdio.h>
#include <sys/personality.h>

int main(void)
{
    personality(PER_LINUX32);
    system("cat /proc/cpuinfo");
    system("uname -a");

    return 0;
}
```



## Personality 32bit setting on 64bit kernel (4/6)

- ARM 64bit Kernel + 32bit User-process

```
root@localhost:~# uname -m  
aarch64
```

```
root@localhost:~# cat /proc/cpuinfo  
processor      : 0  
BogoMIPS      : 48.00  
Features      : fp asimd evtstrm aes pmull sha1 sha2 crc32  
CPU implementer : 0x41  
CPU architecture: 8  
.....
```

## Personality 32bit setting on 64bit kernel (5/6)

- ARM 64bit Kernel + 32bit User-process with **PER\_LINUX32**

```
root@localhost:~# uname -m  
armv8l
```

```
root@localhost:~# cat /proc/cpuinfo  
processor      : 0  
model name    : ARMv8 Processor rev 1 (v8l)  
BogoMIPS     : 48.00  
Features      : half thumb fastmult vfp edsp neon vfpv3 tls vfpv4 idiva  
               idivt lpae evtstrm aes pmull sha1 sha2 crc32  
CPU implementer : 0x41  
CPU architecture: 8  
.....
```

## Personality 32bit setting on 64bit kernel (6/6)

- How to support the compatibility on 64bit kernel.
  - COMPAT\_PSR\_\*\_BIT means the AArch32 CPSR bits to support the compatibility for 32bit user-process.
  - For example for 'thumb' mode,
    - There is no CONFIG\_THUMB2\_KERNEL on ARM 64bit.
    - If COMPAT\_PSR\_T\_BIT is set, the A32/T32 instruction are converted to A64 instruction.

## 32bit process running on 64bit Kernel

- CONFIG\_COMPAT
- Should consider fops->compat\_ioctl() if driver has fops->unlocked\_ioctl()
  - Usually, not in legacy arm drivers
- Architecture dependent arg type of ioctl
  - Need to consider different size of type from 32bit user

## compat\_ioctl: case of tgl

- Legacy driver tgl
  - Bad design of legacy driver
  - But need to support same ioctl user interface
- misc: tizen\_global\_lock: add support for 32bit compat mode from 64bit  
(fixed from tizen devel tree)
  - <https://review.tizen.org/git/?p=platform/kernel/linux-exynos.git;a=commitdiff;h=b6516ba567384295bd906e515e31fef3e412fc19;hp=f874e761defc229f415eeb50e66d5cb6000cfb62>

# compat\_ioctl: case of tgl

```
@@ -764,6 +776,9 @@ static const struct file_operations tgl_ops = {
    .open = tgl_open,
    .release = tgl_release,
    .unlocked_ioctl = tgl_ioctl,
+ #ifdef CONFIG_COMPAT
+     .compat_ioctl = tgl_ioctl,
+ #endif
};
```

```
...
#define TGL_IOC_DUMP_LOCKS    _IOW(TGL_IOC_BASE, TGL_DUMP_LOCKS, void *)
+ #define TGL_IOC_DUMP_LOCKS_COMPAT    W
+     _IOW(TGL_IOC_BASE, TGL_DUMP_LOCKS, unsigned int)
...

@@ -649,6 +649,9 @@ static long tgl_ioctl(struct file *file, unsigned int cmd, unsigned long arg)

    switch (cmd) {
        case TGL_IOC_INIT_LOCK:
+ #ifdef CONFIG_COMPAT
+     case TGL_IOC_INIT_LOCK_COMPAT:
+ #endif
        /* destroy lock with attribute */
        err = tgl_init_lock(session_data, (struct tgl_attribute *)arg);
        break;
```

# 32bit process running on 64bit Kernel

- Alignment PAD in arg of ioctl
  - v4l2-compat-ioc32: fix alignment for ARM64 (merged to mainline)
    - Alignment/padding rules on arm64 and x86 differs

```
$ cat arch/arm64/include/asm/compat.h
...
typedef s64          compat_s64;
...
```

```
$ cat arch/x86/include/asm/compat.h
...
typedef s64 __attribute__((aligned(4))) compat_s64;
...
```

## 32bit process running on 64bit Kernel

- Case of mmap() failiure
  - \_\_USE\_FILE\_OFFSET64 to call \_\_mmap64 from userspace



# What are the challenges on TM2?

---

32bit process running on 64bit kernel

**Issues required to discuss on mainline**



## FPSIMD seg. fault on suspend-to-ram (1/8)

- The Segmentation fault happened after wake up from the suspended state.
  - 32bit user-process such as bash, udevd and so on.
- The fault only happened on 64bit kernel + 32bit user-process.
  - If both kernel and user-process are 64-bit, the crash did not happened.

## FPSIMD seg. fault on suspend-to-ram (2/8)

- But when removing the '-O2' option when building the user process, the issue did not occur.
- With '-O2' option, the toolchain uses the 'FMOV' instead of 'MOV' command.
  - '-O2' is the optimization option for GCC.

## FPSIMD seg. fault on suspend-to-ram (3/8)

- Finally, when using the 'FMOV' assembly command, the segmentation fault occurred.
  - 'FMOV' command is used for FPSIMD on ARM 64bit.
  - 'FMOV' is floating-point move to or from general-purpose register without conversion.
    - FMOV Dd, Xn /\* 64-bit to double-precision \*/
    - FMOV Xn, Dd /\* Double-precision to 64-bit\*/
      - 'Xn' is the 64-bit name of the general-purpose source register.
      - 'Dd' is the 64-bit name of the SIMD and FP destination register.

## FPSIMD seg. fault on suspend-to-ram (4/8)

- Result of 'Dn' register dump between normal and fail case as following:
  - On fail case, 'Dn' registers have garbage data instead of zero or .

# FPSIMD seg. fault on suspend-to-ram (5/8)


- Register dump between success and fail

<Success case for suspend-to-ram>				<Fail case for suspend-to-ram>			
d7	{f = 0x0, u = 0x8020080280200802, s = 0x8020080280200802}			d7	{f = 0x7fffffffffffffff, u = 0x7e2c5ba5727e0e15, s = 0x7e2c5ba5727e0e15}	{f = 5.9347331789315386e+299, u = 9091742513902784021, s = 9091742513902784021}	
	{f = -4.4588500238274385e-308, u = 9232388042942056450, s = -9214356030767495166}			d8	{f = 0x7fffffffffffffff, u = 0x4fdcbf57f44dee9d, s = 0x4fdcbf57f44dee9d}	{f = 5.2011338352281976e+76, u = 5754684808354459293, s = 5754684808354459293}	
d8	{f = 0x0, u = 0x0, s = 0x0}	{f = 0, u = 0, s = 0}		d9	{f = 0x8000000000000000, u = 0xf5eb59012cb4849a, s = 0xf5eb59012cb4849a}	{f = -1.0512031953185022e+260, u = 17720355020399215770, s = -726389053310335846}	
d9	{f = 0x0, u = 0x0, s = 0x0}	{f = 0, u = 0, s = 0}		d10	{f = 0x0, u = 0x531a04477effd23, s = 0x531a04477effd23}	{f = 1.1853291409126618e-283, u = 374256459978898723, s = 374256459978898723}	
d10	{f = 0x0, u = 0x0, s = 0x0}	{f = 0, u = 0, s = 0}		d11	{f = 0x0, u = 0x1272f9b865387e26, s = 0x1272f9b865387e26}	{f = 8.3991572712913294e-220, u = 1329399410395217446, s = 1329399410395217446}	
d11	{f = 0x0, u = 0x0, s = 0x0}	{f = 0, u = 0, s = 0}		d12	{f = 0x0, u = 0x385e0dfcecf4fd6, s = 0x385e0dfcecf4fd6}	{f = 3.5329060230148928e-37, u = 4061699293893709782, s = 4061699293893709782}	
d12	{f = 0x0, u = 0x0, s = 0x0}	{f = 0, u = 0, s = 0}		d13	{f = 0x0, u = 0x148d2d6cf610121c, s = 0x148d2d6cf610121c}	{f = 1.1093798491827732e-209, u = 1480889798482727452, s = 1480889798482727452}	
d13	{f = 0x0, u = 0x0, s = 0x0}	{f = 0, u = 0, s = 0}					

## FPSIMD seg. fault on suspend-to-ram (6/8)

- ARM 64bit kernel handles the FPSIMD registers when context switching as following:

```
/* Thread switching */
struct task_struct __switch_to(
    struct task_struct *prev, struct task_struct *next)
{
    fpsimd_thread_switch(next);
    .....
}
in arch/arm64/kernel/process.c
```



```
void fpsimd_thread_switch(struct task_struct *next)
{
    .....

    struct fpsimd_state *st = &next->thread.fpsimd_state;

    if (__this_cpu_read(fpsimd_last_state) == st
        && st->cpu == smp_processor_id())
        clear_thread_flag(task_thread_info(next),
                        TIF_FOREIGN_FPSTATE);

    else
        set_thread_flag(task_thread_info(next),
                        TIF_FOREIGN_FPSTATE);

    .....
}
in arch/arm64/kernel/fpsimd.c
```

## FPSIMD seg. fault on suspend-to-ram (7/8)

- The `fpsimd_thread_switch()` doesn't consider the specific situation when CPU wakes up from the suspended state.
  - After wake up from the suspended state, the `fpsimd_thread_switch()` has to restore the FPSIMD registers always to prevent the segmentation fault.



## FPSIMD seg. fault on suspend-to-ram (8/8)

- How to fix the segmentation fault.
  - The `fpsimd_thread_switch()` should handle the suspend-to-ram for 32bit user-process.
  - Or `TIF_FOREIGN_FPSTATE` should be always set for next task temporarily as following:

```
void fpsimd_thread_switch(struct task_struct *next)
{
    .....
    set_ti_thread_flag(task_thread_info(next), TIF_FOREIGN_FPSTATE);
    .....
}
in arch/arm64/kernel/fpsimd.c
```

## ARM Generic Timer issue in ARM 64bit (1/4)

- Linux kernel needs the clock sources for timekeeping features.
  - clocksource and sched\_clock()
- The purpose of the clocksource is to provide a timeline for the system that tells you where you are in time.
- sched\_clock() is used for scheduling and timestamping of printk.

## ARM Generic Timer issue in ARM 64bit (2/4)

- ARM arch. provides the Generic Timer for system counter such as clocksource and sched\_clock().
  - physical counter (CNTPCT\_EL0 register in AArch64)
  - virtual counter (CNTVCT\_EL0 register in AArch64)
- ARM 64bit kernel and user space requires the use of virtual counter.
  - ARM 64bit only expose virtual counter(CNTVCT) to user VDSO (Virtual Dynamically Linked Shared Object).

# ARM Generic Timer issue in ARM 64bit (3/4)

- Exynos5433 fails to synchronize the timestamping among CPUs when printing the log with virtual counter as following:

```
[ 0.050577] Mount-cache hash table entries: 8192 (order: 4, 65536 bytes)
[ 0.057208] Mountpoint-cache hash table entries: 8192 (order: 4, 65536 bytes)
[ 0.065307] ASID allocator initialised with 65536 entries
[ 0.094297] EFI services will not be available.
[ 244.881736] Detected VIPT I-cache on CPU1
[ 244.881801] CPU1: Booted secondary processor [410fd031]
[ 5881.039842] Detected VIPT I-cache on CPU2
[ 5881.039887] CPU2: Booted secondary processor [410fd031]
[ 6253.690734] Detected VIPT I-cache on CPU3
[ 6253.690776] CPU3: Booted secondary processor [410fd031]
[ 444.293771] Detected PIPT I-cache on CPU4
[ 444.293775] CPU features: enabling workaround for ARM erratum 832075
[ 444.293812] CPU4: Booted secondary processor [411fd070]
[ 444.309757] Detected PIPT I-cache on CPU5
[ 444.309782] CPU5: Booted secondary processor [411fd070]
[ 444.325756] Detected PIPT I-cache on CPU6
[ 444.325781] CPU6: Booted secondary processor [411fd070]
[ 444.341765] Detected PIPT I-cache on CPU7
[ 444.341790] CPU7: Booted secondary processor [411fd070]
[ 0.211925] Brought up 8 CPUs
```

## ARM Generic Timer issue in ARM 64bit (4/4)


- How to fix the issue about random offset on ARM 64bit.
  - Initialize the offset (CNTOFF) to use the Generic Timer on bootloader.
    - Generic Timer comes up with an uninitialized offset (CNTOFF) between virtual and physical counters.
    - Each core gets a different random offset.
  - Use the physical counter if VDSO is not used.

## Deadlock between regmap and CCF (1/5)

- ABBA deadlock happened between Regmap and CCF (Common Clock Framework).
- Mutex for Regmap vs. Mutex for `clk_prepare()`.
- Example,
  - the MFD device includes the both PMIC and clock device such as Samsung S2MPS1x series.

# Deadlock between regmap and CCF (2/5)

- Example of ABBA deadlock



< ABBA deadlock scenario on TM2 with s2mps14 >

## Deadlock between regmap and CCF (3/5)

- Fix the deadlock between regmap and CCF
  - `clk_prepare()` should be used on probe and then `clk_enable()` will be used on runtime temporarily.
  - `clk_enable()` uses the spinlock instead of mutex.
  - For example,
    - i2c: s3c2410: fix ABBA deadlock by keeping clock prepared
      - <https://patchwork.kernel.org/patch/5659351/>
    - i2c: exynos5: Fix possible ABBA deadlock by keeping I2C clock prepared
      - <https://patchwork.kernel.org/patch/8859551/>



# Deadlock between regmap and CCF (4/5)

- Fix the deadlock between regmap and CCF
  - Use the spinlock on the regmap-i2c temporarily.
    - regmap-mmio uses the 'spinlock' for locking mechanism.
    - regmap-i2c uses the 'mutex' for locking mechanism.
    - regmap-spi uses the 'mutex' for locking mechanism.

```
struct regmap_bus regmap_mmio = {  
    .fast_io = true,  
};  
in drivers/base/regmap/regmap-mmio.c  
  
struct regmap_bus regmap_i2c = {  
    .fast_io = false,  
};  
in drivers/base/regmap/regmap-i2c.c  
  
struct regmap_bus regmap_spi = {  
    .fast_io = false,  
};  
in drivers/base/regmap/regmap-spi.c
```

```
if (bus->fast_io) {  
    spin_lock_init(&map->spinlock);  
    map->lock = regmap_lock_spinlock;  
    map->unlock = regmap_unlock_spinlock;  
} else {  
    mutex_init(&map->mutex);  
    map->lock = regmap_lock_mutex;  
    map->unlock = regmap_unlock_mutex;  
}  
in drivers/base/regmap/regmap.c
```

# Deadlock between regmap and CCF (5/5)


- How to fix the deadlock.
  - It is not a fundamental solution to use the spinlock instead of mutex.
  - The locking idea to fix the deadlock was suggested on mainline with RFC patches.
    - [RFC 00/17] clk: Add per-controller locks to fix deadlocks
      - <https://lkml.org/lkml/2016/8/16/442>

## Dependency between power domain and CCF (1/6)

- The graphics h/w modules do not work after wakes up from the suspended state.
- The graphics-related clocks are initialized after wakes up from the suspended state.
  - To save and restore the clock registers on CCF (Common Clock Framework) for the suspend-to-RAM.

## Dependency between power domain and CCF (2/6)


- In exynos5433, the clock domain belongs to the power domain about display modules.



- But, CCF does not support the runtime PM. The clock controller is not able to make the dependency with power domain.


# Dependency between power domain and CCF (3/6)

- Clock relationship in Exynos5433




# Dependency between power domain and CCF (4/6)

- Clock relationship in Exynos5433



# Dependency between power domain and CCF (5/6)

- Clock relationship in Exynos5433



## Dependency between power domain and CCF (6/6)

- How to fix the issue about dependency
  - CCF should support the runtime PM interface for the power domain.
  - The patches were posted to support the runtime PM for clock controller.
    - [PATCH v2 0/5] Add runtime PM support for clocks (on Exynos SoC example)
      - <http://www.spinics.net/lists/arm-kernel/msg532798.html>



## Decompression of ARM 64bit kernel image

- ARM 64bit kernel does not support the decompression of kernel image.
- Using decompression feature of u-boot bootloader for compressed kernel image if you use the compressed kernel image.

# More issues

---



## TODO for TM2

- Exynos5433 Device-Tree
- Exynos5433-TM2/TM2E Device-Tree
- Support the multiple IORESOURCE\_MEM for Pinctrl
- Peripheral devices for TM2
  - Touchscreen/key, Fuel-gauge/Charger, Sensorhub and so on.

# Demo

---



# Thank You!

---



# References (cont.)

- Tizen
  - <http://www.tizen.org>
- ARMv8-A Reference Manual
  - <http://infocenter.arm.com/help/index.jsp?topic=/com.arm.doc.set.architecture/index.html>
- ARMv8-A Architecture
  - <http://www.arm.com/products/processors/armv8-architecture.php>
- KASAN
  - <https://www.kernel.org/doc/Documentation/kasan.txt>
- UBSAN
  - <https://www.kernel.org/doc/Documentation/ubsan.txt>
- PSCI (Power State Coordinate Interface)
  - <http://infocenter.arm.com/help/index.jsp?topic=/com.arm.doc.den0022c/index.html>
- HMP git repository by linaro
  - <http://git.linaro.org/?p=arm/big.LITTLE/mp.git>
- IKS (In Kernel Switcher)
  - [https://events.linuxfoundation.org/images/stories/slides/elc2013\\_poirier.pdf](https://events.linuxfoundation.org/images/stories/slides/elc2013_poirier.pdf)
- ARM Generic Timer (cont.)
  - [https://www.kernel.org/doc/Documentation/devicetree/bindings/arm/arch\\_timer.txt](https://www.kernel.org/doc/Documentation/devicetree/bindings/arm/arch_timer.txt)
  - <http://infocenter.arm.com/help/index.jsp?topic=/com.arm.doc.den0024a/BABGBFBF.html>

# References

- ARM Generic Timer
  - commit 65b5732d241b8 (“clocksource: arch\_timer: Allow the device tree to specify uninitialized timer registers”)
  - commit d6ad36913083d (“clocksource: arch\_timer: Only use the virtual counter (CNTVCT) on arm64”)
- GCC option ‘-O2’
  - <https://gcc.gnu.org/onlinedocs/gcc/Optimize-Options.html>
- ‘FMOV’ assembly command
  - [http://www.keil.com/support/man/docs/armclang\\_asm/armclang\\_asm\\_pge1427897629393.htm](http://www.keil.com/support/man/docs/armclang_asm/armclang_asm_pge1427897629393.htm)
- Fix ABBA deadlock patch between regmap and CCF
  - i2c: s3c2410: fix ABBA deadlock by keeping clock prepared
    - <https://patchwork.kernel.org/patch/5659351/>
  - i2c: exynos5: Fix possible ABBA deadlock by keeping I2C clock prepared
    - <https://patchwork.kernel.org/patch/8859551/>
  - [RFC 00/17] clk: Add per-controller locks to fix deadlocks
    - <https://lkml.org/lkml/2016/8/16/442>