

Gerber file generation for PCAD 2001

David Wentzloff

david@wentzloff.com

781-322-7769

Main Tasks Explained in This Document:

- A. Finalize PCB design and check it
 - B. Generate GERBER files
 - C. Generate N/C Drill files
 - D. Verify the GERBER files look correct
-

A. Finalize PCB design and check it

- 1. Run DRC (Utils > DRC...) and compare the PCB netlist with the schematic netlist
- 2. Pour all copper pours
- 3. Silkscreen line width is recommended to be at least 7mils

B. Generate GERBER files

- 4. Add text at the top left of the design, outside the board perimeter, that says the layer name in the layer (i.e. type top copper in the 'top' layer, bottom copper in the 'bottom' layer, ...). Name the following layers for a 2 layer board
 - 4.1. Top copper
 - 4.2. Top silk
 - 4.3. Top solder mask
 - 4.4. Bottom copper
 - 4.5. Bottom silk
 - 4.6. Bottom solder mask
- 5. Bring up the File Gerber Out menu (File > Export > Gerber...), then click Setup Output Files...
- 6. From the Setup Output Files dialog, add each of the following layers and options
 - 6.1.

Layers:	Top, Board
File Extension:	TOP
Options:	Pads, Vias
 - 6.2.

Layers:	Bottom, Board
File Extension:	BOT
Options:	Pads, Vias

6.3.

Layers: Top Silk, Board
File Extension: TSK
Options: RefDes, Type, Value

6.4.


Layers: Bottom Silk, Board
File Extension: BSK
Options: RefDes, Type, Value

6.5.

Layers: Top Mask, Board
File Extension: TMK
Options: Pads, Vias, Pad/Via Holes


6.6.

Layers: Bottom Mask, Board
File Extension: BMK
Options: Pads, Vias, Pad/Via Holes




7. Click Close in the Setup Output Files dialog, then click Apertures... in the File Gerber Out dialog


7.1. Verify Pad/Via holes is unchecked, and the other options are all checked, then click Auto and Close




8. From the File Gerber Out dialog, click Drill Symbols... In the Drill Symbol Assignments dialog, click Automatic Assign, then Close



9. From the File Gerber Out dialog, click Gerber Format... Select Inches, 4.4 format, and check Include aperture definitions (as RS-274-X mass parameters). Click Close




10. The final File Gerber Out dialog should look like the following. Click Generate Output Files and then Close.



C. Generate N/C Drill files

11. Select File > Export > N/C Drill File to bring up the File N/C Drill dialog. Click Setup Output Files...

11.1. Select all signal and plane layers, file extension should be NCD, check All Holes, and verify the Output Path is correct. Then click Add and Close.



11.2. Click Tools, then Unassign All, Auto, and Close

Hole	Plated	Tool
Hole 15.0mil	Yes	T01 15.0mil
Hole 20.0mil	Yes	T02 20.0mil
Hole 30.0mil	Yes	T03 30.0mil
Hole 38.0mil	Yes	T04 38.0mil
Hole 43.3mil	Yes	T05 43.3mil
Hole 60.0mil	Yes	T06 60.0mil
Hole 67.0mil	Yes	T07 67.0mil
Hole 140.0mil	Yes	T08 140.0mil

Hole
Plated: Yes
Diameter: 15.0mil

Tool
Tool code: 1
Diameter: 15.0mil

Assign... Unassign Unassign All

Automatic Describe/Assign
☒ Clear current tools Auto

Close

11.3. For the N/C Drill Format, use the following settings

N/C Drill Format

Output Units
☒ Inches
☐ Millimeters

Output Code Type
☐ EIA Odd
☐ ASCII Even
☒ ASCII N_gne

Zero Suppression
☒ Leading
☐ Trailing
☐ None

Close

11.4. Click Generate Output Files and Close

D. Verify the GERBER files look correct

12. Verify you design by importing the GERBER and N/C Drill files into a free GERBER viewer such as GC Prevue available from <http://www.graphiccode.com/>